


B4. FIRST 4 CARS TRIGGER THE STUNTS.






B5. REMAINING 4 CARS MAKE A SECOND PASS.



INCLUDES 1 VEHICLE. ADDITIONAL VEHICLES SOLD SEPARATELY. NOT FOR USE WITH SOME HOT WHEELS® VEHICLES.

CONNECT & COMBINE TRACK BUILDER STUNTS AND ACCESSORIES TO CREATE TONS OF DIFFERENT SET-UPS!





EACH SOLD SEPARATELY, SUBJECT TO AVAILABILITY.

PERFORMANCE TIPS

- Q. My car keeps crashing on the tracks for no reason. What is the problem?**
- A. Clear all obstructions on the tracks. Adjust track side walls at each connection point.**


- Q. My car keeps slowing down by itself on the tracks.**
- A. Lint may collect around your car's axles. This may cause the car to run slowly. Use tweezers or a toothpick to remove lint.**



©2015 Mattel. All Rights Reserved. Mattel, Inc., 636 Girard Avenue, East Aurora, NY 14052, U.S.A. Consumer Services 1-800-524-8697. Mattel U.K. Ltd., Vanwall Business Park, Maidenhead SL6 4UB. Helpline 01628 500303. Mattel Australia Pty., Ltd., Richmond, Victoria, 3121. Consumer Advisory Service - 1300 135 312. Mattel East Asia Ltd., Room 503-09, North Tower, World Finance Centre, Harbour City, Tsingshatsui, HK, China. Tel.: (852) 3185-6500. Diimport & Diedarkan Oleh: Mattel Southeast Asia Pte. Ltd., No 19-1, Tower 3 Avenue 7, Bangsar South City, No 8, Jalan Kerinchi, 59200 Kuala Lumpur, Malaysia. Tel: 03-78803817, Fax: 03-78803867.



TRACK BUILDER
VOLCANO BLAST



COLORS AND DECORATIONS MAY VARY.



service.mattel.com
HOTWHEELS.COM




CKW72-097061
1100317334-DOM

PLEASE KEEP THESE INSTRUCTIONS FOR FUTURE REFERENCE AS THEY CONTAIN IMPORTANT INFORMATION.



CONTENTS



APPLY LABELS



ASSEMBLY



TO PLAY

